BULLETIN - PLEASE READ!

TECHNICAL BULLETIN

Wobble Box Assembly Instructions

- 1. Check all cover bolts assuring that they are tight.
- 2. Check the needle bearings in the wobble box mount. They should be replaced with new bearings to prevent premature failure.
- 3. Fill wobble box with the proper oil to the proper oil level as directed in the machine's owner's manual.



1020 22nd Ave., Rock Valley, IA 51247 Tel: 800-657-4343 Fax: 800-511-0516 www.aiproducts.com

